

Baldwin County Highway Department
Speed Limit Change Checklist

Location: County Road 93 (Sunset Dr. to Faircloth Rd)
Functional Classification: Local/Rural
Current Posted Limit: 45-SB MPH Proposed Limit: 35 MPH
35-NB

Reason for Speed Limit Change:

Inconsistencies in the speed zone
between Sunset Dr. and Faircloth Rd.

Latest Traffic Data:

Date traffic counters set out: 10/12/20 Length of Count: 48 Hrs
ADT: 896
85th percentile: 61 MPH Average: 39 MPH
Pace: 26-35 MPH
Percentage of Vehicle in Pace: 40.0 %
Percentage of Commercial Vehicles: 18.0 %

Roadway Geometry:

Are there any sight-distance issues? No

If yes, explain:

None

Is the Clear Zone in compliance within established County standards? yes

Does the geometry of the roadway meet established County standards? yes

Method used to determine compliance:

Ball Bank (CARS): _____ Survey: _____ Visual: ✓

Roadway width: 20-22'
Roadway length: 0.75 miles

Density: Heavy: Moderate: Light:

Accident data (previous three years): N/A

Total number of accidents:

Total number of fatality accidents:

Total number of injury accidents:

Total number of property damage only accidents:

Signage:

Are there any existing advisory speed limit signs: No

Advisory Speed: None

Locations: None

If posted at proposed speed, will there be any required advisory speed limit signs? No Advisory Speed: None

If yes, location:

None

Is the road in the Police Jurisdiction of a municipality? No


Has the municipality been advised of the proposed change? N/A

Recommendation to Baldwin County Commission:

Adjust the speed limit between Sunset Dr and Faircloth so that the speed limit is 35 mph in both directions.

Signature: Troy Smith

Date: 10/27/20



Between Sunset Dr and Faircloth Rd
 Southbound is 45 MPH
 Northbound is 35 MPH
 Make this section 35 MPH

North of Faircloth Rd is 25 MPH

South of Sunset Drive is 35 MPH