## Baldwin County Highway Department Speed Limit Change Checklist

Location: Dreenleaf Drive
Functional Classification: Local/Rural
Current Posted Limit: None MPH Proposed Limit: 25 MPH
Reason for Speed Limit Change: This road is currently unposted.
Latest Traffic Data:
Date traffic counters set out: 3/22/18 Length of Count: 24 Hrs ADT:
Roadway Geometry: Are there any sight-distance issues?NO If yes, explain: N/A
Is the Clear Zone in compliance within established County standards? <u>\\e\g\g}</u>
Does the geometry of the roadway meet established County standards: <u>yes</u>
Method used to determine compliance:  Ball Bank (CARS): Survey:Visual:

Roadway width: 22 feet Roadway length: 0.27 miles
Roadway length: 0.27 miles
<i>Density</i> : Heavy: Moderate: Light:✓
Accident data (previous three years): N/A  Total number of accidents:  Total number of fatality accidents:  Total number of injury accidents:  Total number of property damage only accidents:
Signage:  Are there any existing advisory speed limit signs:  Advisory Speed: NOne  Locations: N/A
If posted at proposed speed, will there be any required advisory speed limit signs?NO Advisory Speed:NO If yes, location:
Is the road in the Police Jurisdiction of a municipality? ND Has the municipality been advised of the proposed change? NA Recommendation to Baldwin County Commission:
Establish a speed limit of 25 mpH as recommended in agarda.
recommended in agenda.
Signature: Twy Inth Date: 4/27/2018
Date: 4/27/2018 ()

## Baldwin County Highway Department Speed Limit Change Checklist

Location: Chasewood Place
Functional Classification: Local/Rural
Current Posted Limit: None MPH Proposed Limit: 25 MPH
Reason for Speed Limit Change: This road is currently unposted.
Latest Traffic Data:
Date traffic counters set out: 3/22/18 Length of Count: 24 Hrs ADT:
Roadway Geometry: Are there any sight-distance issues?NO If yes, explain: N/A
Is the Clear Zone in compliance within established County standards?/e 5
Does the geometry of the roadway meet established County standards: <u>yes</u>
Method used to determine compliance:  Ball Bank (CARS): Survey:Visual:

Roadway width: 22 feet  Roadway length: 0.19 mile 5
Roadway length: 0.19 miles
Density: Heavy: Moderate: Light: _✓  Accident data (previous three years): N/A  Total number of accidents:  Total number of fatality accidents:
Total number of injury accidents:
Total number of property damage only accidents:
Signage:  Are there any existing advisory speed limit signs:NO  Advisory Speed:NOne_  Locations:N/A
If posted at proposed speed, will there be any required advisory speed limit signs?NO Advisory Speed:NO If yes, location:
Is the road in the Police Jurisdiction of a municipality? ND  Has the municipality been advised of the proposed change? NA  Recommendation to Baldwin County Commission:  Establish a seed Limit of 25 meth as
Establish a speed limit of 25 mpH as recommended in agarda.
Signature: Twy Smtt  Date: 4/27/2018

