## Baldwin County Highway Department Speed Limit Change Checklist

Location: John Bauer Rd (CR55 west to Eom)
Functional Classification: Local Rural
Current Posted Limit: N/A MPH Proposed Limit: 25 MPH
Reason for Speed Limit Change:  John Bauer Rd 15 a recent Durt Road Pawing  project and is currently imposted.
Latest Traffic Data:
Date traffic counters set out: 2/8/19 Length of Count: 72 Hrs  ADT:
If yes, explain:
Is the Clear Zone in compliance within established County
Does the geometry of the roadway meet established County standards: <u>yes</u>
Method used to determine compliance:  Ball Bank (CARS): Survey:Visual:

Roadway width: 20' Roadway length: 0.50 miles
Roadway length: 0.50 miles
<i>Density</i> : Heavy: Moderate: Light:✓
Accident data (previous three years): N/A
Total number of accidents:
Total number of fatality accidents:
Total number of fatality accidents:  Total number of injury accidents:
Total number of property damage only accidents:
Signage:
Are there any existing advisory speed limit signs:
Advisory Speed: None
Locations: None
If posted at proposed speed, will there be any required advisory speed limit signs? Advisory Speed: MO If yes, location: MO
Is the road in the Police Jurisdiction of a municipality?NO_ Has the municipality been advised of the proposed change?N/A
Recommendation to Baldwin County Commission:  Establish a speed limit of 25 me H  as recommended.



## JOHN BAUER RD (COUNTY RD 55 WEST TO EOM) SPEED



