


FAIRCLOTH ROAD SPEED LIMIT





Baldwin County Highway Department Speed Limit Change Checklist

Location: Farcloth Rd (CR91 to Jones LN)
Functional Classification: Local Regal Current Posted Limit: N/A MPH Proposed Limit: 45 MPH
Reason for Speed Limit Change: This section of road is currently not posted.
Latest Traffic Data:
Date traffic counters set out: 10/7/19 Length of Count: 72 Hrs ADT:
Roadway Geometry: Are there any sight-distance issues?NO If yes, explain:
Is the Clear Zone in compliance within established County standards?
Does the geometry of the roadway meet established County standards: $\frac{\sqrt{e5}}{}$
Method used to determine compliance: Ball Bank (CARS): Survey:Visual:

Roadway width:20' Roadway length:0.50miles
<i>Density</i> : Heavy: Moderate: Light:
Accident data (previous three years): N/A Total number of accidents: Total number of fatality accidents: Total number of injury accidents: Total number of property damage only accidents:
Signage: Are there any existing advisory speed limit signs:NO Advisory Speed:NOne Locations:None
If posted at proposed speed, will there be any required advisory speed limit signs?NO Advisory Speed: _None If yes, location:
Is the road in the Police Jurisdiction of a municipality?
Recommendation to Baldwin County Commission: Establish a speed limit OF 45 mpH as recommended
Signature: Date: 2/5/20

Baldwin County Highway Department Speed Limit Change Checklist

Location: Faircloth Rd (Jones Ln to CR 93) Functional Classification: Local/Rural Current Posted Limit: N/A MPH Proposed Limit: 30 MPH
Reason for Speed Limit Change: a 0.48 mile Section OF this road is a recent dirt road paving project. The remaini 0.24 miles is previously unposted.
Latest Traffic Data:
Date traffic counters set out: 1/7/20 Length of Count: 48 Hrs ADT:
Roadway Geometry: Are there any sight-distance issues? <u>Yes</u> If yes, explain: 3 curves located on this section OF road
Is the Clear Zone in compliance within established County standards?
Does the geometry of the roadway meet established County standards: <u>\\essigns_5</u>
Method used to determine compliance: Ball Bank (CARS): Survey:Visual:

Roadway width: 20' Roadway length: 0.72 miles
Roadway length: 0.72 miles
Density: Heavy: Moderate: Light:
Accident data (previous three years): N/A
Total number of accidents:
Total number of fatality accidents:
Total number of injury accidents:
Total number of property damage only accidents:
rotar name of property duringe only decidents.
Signage:
Advisory Speed: 10 mPH
Are there any existing advisory speed limit signs: <u>Yes</u> Advisory Speed: 10 mpH Locations: mid point of this section or road.
If posted at proposed speed, will there be any required advisory
speed limit signs? Yes Advisory Speed: Varying 10-15 mPH
If yes, location:
Is the road in the Police Jurisdiction of a municipality? NO
Has the municipality been advised of the proposed change? N/A
Recommendation to Baldwin County Commission:
Establish a speed Limit OF 30 mpH as
recommended
Signature
Signature: 2/5/20